₹ €	****		
No. or caries acceived			Form C-103 Supersedes Old
DISTRIBUTION	*		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION Effective 1-1-65		
FILE	 		Sa. Indicate Type of Leono
U.5.G.S.			State Fee X
LAND OFFICE		·•	5. State Oil & Gua Leane No.
OPERATOR			
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR INSCRIBED TO THIS ON TO THE PLACE TO A DIFFERENT RESERVOIR. 100 NOT USE THIS FORM FOR INSCRIPTION FOR PERFORMANCE OF THE PROPERTY OF THE PROPE			7. Unit Agreement Fame
O'L X GAS OTHER-			
2. Name of Operator			6. Ferm of Lease Name
The Maurice L. Brown Company			Rogers
Sutton Place Bldg. Suite 200, Wichita, Kansas 67202			1
4. Lecation of Well	660' FEET FACH THE West		Vada Penn
The second secon	SECTION 6 TOWNSHIP 98		
THE LINE, S	ECTION TOWNSHIP	RANGE NMPM.	
	15. Elevation (Show whether 4211.3 GR	TDF, RT, GR, etc.)	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
[-1	<u> </u>		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	- Con the Medical frame
PULL OR ALTER CASING		OTHER	
OTHER			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
1. Moved in and rigged up DA&S Pulling Rig. Pulled and stood back 2 3/8" tubing			
2. Spotted 35 sx. cement through tubing @6753'. Squeezed to 1600#. Tagged top			
at 6561!			
3. Shot $5\frac{1}{2}$ " casing at 6282'. Pulled and layed down 195 jts.(6285').			
4. Loaded hole with 10# salt gell mud.			
5. Spotted 40 sx. cement through tubing at 6322' across 51" stub.			
6. Spotted 50 sx. cement through tubing at 5466' across top of Glorieta. Tagged top of cement at 5345'.			
7. Spotted 40 sx. cement through tubing at 4095'. Tagged top of plug at 4050'.			
8. Spotted 40 sx. cement through tubing at 4050'. 9. Shot 8 5/8" casing at 1191'. Layed down 29 jts. 8 5/8" casing. Total tally			
of 12031.			
10 Spotted 50 sy cement through tubing at 1240' across 8 5/8" casing stub.			
11. Spotted 50 sx. cement through tubing at 465' across 13 3/0" casing seat.			
12. Set 10 sx. cement at surface and erected dry hole marker.			
13. Rigged down casing pullers. 14. Filled cellar and mud pit and cleaned location.			
Job completed on 9-11-76. This location is ready for your inspection.			
· · · · · · · · · · · · · · · · · · ·			
The state of the s			
18. I sereby certify that the information above is true and complete to the best of my knowledge and belief.			
11 11	1 . 1		

OIL & GAS INSPECTOR

MAYE APR 2 1979

COMM