to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department	Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	<b>OIL CONSERVATION DIVISION</b>	WELL API NO.
P.O. Box 1980, Honor, NM 88240 <u>DISTRICT II</u> Santa Fe, New Mexico 87504-2088		30-025-23043
P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE XX FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. K-2311
( DO NOT USE THIS FORM FOR PI DIFFERENT RESI	TICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ERVOIR. USE "APPLICATION FOR PERMIT" C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL GAS WELL X WELL	OTHER	Champlin AQD State
2. Name of Operator YATES PETROLEUM CORPO	DRATION	8. Well No.
3. Address of Operator		9. Pool name or Wildcat
105 South 4th St., Ar	tesia, NM 88210	Bagley Permo Penn, North
<ol> <li>Well Location</li> <li>Unit Letter <u>F</u> : <u>1</u></li> </ol>	980 Feet From The North Line and 21	30 Feet From The West Line
Section 8	Township 11S Range 33E	NMPM Lea County
	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4304' GR	
11. Check	Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	•••	BSEQUENT REPORT OF:
PULL OR ALTER CASING CASING TEST AND CE		
DTHER:		
		well to production XX
work) SEE RULE 1103. 1-31-97 - Moved in an with 7000#. TOOH and down. Shut down. 2-1-97 - Nippled up rods. Unseat pump. in BOP to 2-7/8". Si 2-4-97 - TIH with bi Torqued up. Rigged Worked pipe up and do 2-5-97 - TOOH with to 9145'. TOOH. Indication jars, drill collars to get thru up and do bumper sub, jars, co	Tations (Clearly state all periment details, and give periment dates, inc. nd rigged up pulling unit. Set new de d laid down rods. Rods parted. Relea BOP. Pulled tubing to fluid and swabl TOOH and laid down all rods. TOOH we hut well in. t, scraper and tubing. Set down at 91 up pump truck. Pumped 160 bbls 2% KC own. Set down at 9145'. Pulled up 1 ubing. TIH with 4-1/2" OD impression ates casing pin rolled in. TIH with and 2-7/8" tubing. Tagged at 9145'. own. TIH 55'. Set down at 9200'. To llars and 2 stands tubing. Shut well me operations THANK	Juding estimated date of starting any proposed eadman anchors. Picked up on rods ased tubing anchor. Set flange oed down. Pulled up to parted ith 2-3/8" tubing. Changed rams 145'. Rotated with tongs. L down annulus - no circulation. joint. Shut well in. block on sandline. Set down at 4-1/2" casing swedge, bumper sub, Swedged out tight spot, 3 points DOH. TIH with 4-3/4" swedge, in. INUED ON NEXT PAGE:
work) SEE RULE 1103. 1-31-97 - Moved in an with 7000#. TOOH and down. Shut down. 2-1-97 - Nippled up rods. Unseat pump. in BOP to 2-7/8". Si 2-4-97 - TIH with bi Torqued up. Rigged Worked pipe up and de 2-5-97 - TOOH with to 9145'. TOOH. Indice jars, drill collars to get thru up and de bumper sub, jars, co I hereby certify that the information above in the showATURE # Masty Kless TYPE OR PRINT NAME Rusty Kless	erations (Clearly state all periment details, and give periment dates, inc nd rigged up pulling unit. Set new de d laid down rods. Rods parted. Relea BOP. Pulled tubing to fluid and swabl TOOH and laid down all rods. TOOH we hut well in. t, scraper and tubing. Set down at 9 up pump truck. Pumped 160 bbls 2% KC own. Set down at 9145'. Pulled up 1 ubing. TIH with 4-1/2" OD impression ates casing pin rolled in. TIH with and 2-7/8" tubing. Tagged at 9145'. own. TIH 55'. Set down at 9200'. To llars and 2 stands tubing. Shut well The and 2 stands tubing. CONT Mark Operations in	<pre>luding estimated date of starting any proposed eadman anchors. Picked up on rods ased tubing anchor. Set flange oed down. Pulled up to parted ith 2-3/8" tubing. Changed rams 145'. Rotated with tongs. L down annulus - no circulation. joint. Shut well in. block on sandline. Set down at 4-1/2" casing swedge, bumper sub, Swedged out tight spot, 3 points DOH. TIH with 4-3/4" swedge, in. INUED ON NEXT PAGE: Technician DATE Feb. 12, 1997</pre>

YATES PETROLEUM CORPORATION Champlin AQD State #1 Section 8-T11S-R33E Lea County, New Mexico

## SUNDRY NOTICE CONTINUED:

2-6-97 - TIH with casing swedge, bumper sub, jars, drill collars and tubing. Tagged tight spot at 9145'. Swedged out. TOOH. TIH with 4-3/4" bottom hole tapered mill, bumper sub, jars, drill collars and tubing. Tagged at 9145'. Reamed out clean. No drag up or down. Pulled 20 stands. Shut well in.

2-7-97 - TOOH with tapered mill. TIH with bit, drill collars and tubing. Tagged at 9200'. Drilled top slips off CIBP. Pushed CIBP down to 9354'. TOOH. Laid down drill collars. TIH with 5-1/2" packer and tubing. Set packer at 9105'. Loaded annulus with 90 bbls. Tested to 500#.

2-8-97 - Acidized perforations 9145-9222' (Bough) (via 2-7/8" tubing) with 1500 gallons 15% iron control HCL acid and ball sealers. Swabbing.

2-9-97 - Swabbed. Shut well in.

2-10-97 - Swabbed. Shut well in.

2-11-97 - Bled well down. Pumped 60 bbls 2% down tubing. Released packer. TOOH. Nippled down manual BOP. Nippled up hydril BOP. TIH with sub pump. Released well to production department.

Rusty Klein Operations Technician Feb. 12, 1997