

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
GEOLOGICAL SURVEY

LEASE ORIGINATOR'S NAME
N.M. 1466

SUNDRY NOTICES AND RECORDS OF WELLS

(Do not use this form for a notice of completion or report of a different reservoir.
Use "ANALYTICAL DATA SHEET" for each proposal.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Re-entry	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Wood Oil Distributing Company	8. FARM OR LEASE NAME Coll Federal
3. ADDRESS OF OPERATOR 415 North Grant, Odessa, Texas 79760	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1950' FWL, Sec 8 T-9S R-3SE Lea County, New Mexico	10. FIELD AND FOM, OR WILDERNESS Vada Farm
14. PERMIT NO.	11. SEC. T. R. M. OR B. L. A. SURVEY OR AREA Sec 8 T-9S R-3SE
15. ELEVATIONS (Show whether DF, RT, GA, etc.) 4200' KB	12. COUNTY OR PARISH Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	WELL OR ADJAC. CASING ☐	WATER SHUT-OFF ☐	REPAIR WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ADJAC. CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGING DEPTH ☒	(Other) WELL STATUS ☒	

(*) Report results of multiple completion or Well Completion or Abandonment Report of Log to 17.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated rate of proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths of all intervals pertinent to this work.)

1. Cleaned out to top of 8 5/8 casing at 1365'. Run 8 5/8 casing to 1227' (casing stuck).
2. Drilled & cleaned out to 5752' ground level. Logged well and did not find 5 1/2 casing stub.
3. Operations have been suspending pending acquisition of 7 5/8 Flash joint casing to be run to approximately 1410' GL. ~~Casing will be cemented and well shutback at 5000' for drilling to top of 9500'.~~
4. Mud in hole has a weight of 9.5 #/gal min.

18. I hereby certify that the foregoing is true and correct.

SIGNED Chay A. Mason TITLE Engineer DATE 3-1-75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY.

ACCEPTED FOR RECORD
OCT 1 1975
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO