

P. O. BOX 1876

MIDLAND, TEXAS

September 30, 1969

Sam Boren
1102 Vaughn Building
Midland, Texas, 79701

Gentlemen:


The following is the inclination report on your Mather "D" #1, located in Lea County, New Mexico

<u>Depth (feet)</u>	<u>Angle of Inclination (degrees)</u>	<u>Displacement (feet)</u>	<u>Accumulative Displacement (feet)</u>
412	1/4°	1.81	1.81
1406	1/4°	4.37	6.18
2405	3/4°	13.08	19.26
3032	1°	10.97	30.23
3925	1/4°	3.93	34.16
4720	1/4°	3.50	37.66
5190	1-1/4°	10.25	47.91
5707	1-1/4°	11.27	59.18
6561	1-1/4°	10.08	69.26
7347	1°	13.75	83.01
8160	3/4°	10.65	93.66
8307	1-3/4°	4.48	98.14
8655	3°	18.20	116.34
9167	1-3/4°	15.62	131.96
9680	1/2°	4.46	136.42
10314	1/2°	5.51	141.93
10400	1/2°	.75	142.68

Total Displacement 142.68


Sincerely yours,

F W A Drilling Company, Inc.



Clint Hurt

Before personally appeared Clint Hurt known to me to be the person whose name is subscribed above. Witnesseth my hand this the 30th day of September, 1969.



Jackie Snoddy
Notary Public in and for Midland
County, Texas.

11 Dec 1959

100-441108-100

[illegible][illegible][illegible]

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific information required.

1. *Phragmites australis* (Cav.) Trin. ex Steud.

Trial	Control (n=10)	MCI (n=10)	AD (n=10)
1	85	75	65
2	80	70	60
3	75	65	55
4	70	60	50
5	75	65	55

1. On the 10th of May 1944, the following was received from the
British Consulate, London:

100