

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
E-1442	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.	8. Farm or Lease Name Mathers Comm.
3. Address of Operator P. O. Box 1861 - Midland, Texas 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>766</u> FEET FROM THE <u>South</u> LINE AND <u>1874</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Wildcat North Bagley Penn
11. Elevation (show whether DF, RT, GR, etc.) 4265' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Clean out</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-22 MIRU X pert WS/ Attemp circ hole w/300 bbls 2% KCL would not circ/POH w/2-7/8 tbg(9414)/ RIH w/4-9/16 flat Btm shoe and 60' 4" wash pipe, jars, 4-3½ DC on 2-7/8 tbg to 2650.
(Reverse)
- 2-23 Finish/Hw/shoe washpipe jars DC and tbg/tag fish @ 9539 attemp circ w/400bbl 2%KCL w/22sx paper w/no circ/dry drill (conv.) 9539-9553/POH to 8700 w/4.5 pts drag.
- 2-24 Work stuck tbg 2 hrs worked down from 8700 to 8913 pump 80 bbls down csg/pulled free/ POH w/shoe 2 jts washpipe, jars DCs & tbg Rec no fish/RIH w/4-1/8 overshot w/2-3/8 grapple jars bumper sub 6-3½ DC on 2-7/8tbg/tag fish @ 9514 push down hole to 9524 latch fish/jar ½ hr fish began moving up hole would not go down/POH to 8500.
- 2-25 Finish POH w/over shot & fishing ass'y Rec 15.89' 2-3/8 tbg last 4' tbg split showing heavy corrosion leaving top of fish @ 9540 RIH w/4-9/16 flat btm shoe kut Rite shoe 4" wash pipe 6 3½ DC, jars, on 2-7/8 tbg to 9400.
- 2-26 Lower shoe tag & washover RBP 9551-9555 4' in 5 hrs No progress last hr/PPH w/washover ass'y found shoe wore smooth/RIH w/new 4-9/16 shoe 2 jts wash pipe jars 6-3½ DC on 2-7/8 tbg to 2000'.

(cont.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE Acct. Assist. II DATE 3-31-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 5 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 4 1983
O.C.D.
HOLDS OFFICE