

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-5212	
7. Unit Agreement Name	
-	
8. Farm or Lease Name	
Graham-State	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Bagley, N. (U. Penn)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐

2. Name of Operator
Southland Royalty Company

3. Address of Operator
1405 Wilco Bldg., Midland, Texas 79701

4. Location of Well
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 11-S RANGE 33-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4267' RKB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned by Bonanza Casing Pulling Co., Hobbs, New Mexico.
Work completed 3-18-74.
Set plugs as follows:
Set 5½" WLBP @ 6556' w/4 sx cmt.
Shot & pulled 4105' of 5½" csg.
Spotted 65 sx plug 3905-4105'.
Shot off 8 5/8" @ 2445' (stuck), 2185' (stuck), 2023' (stuck), 1794' (stuck), 1630' (stuck), 1268' (stuck), 1170' worked casing loose.
Spotted 65 sx plug 1120-1220'.
Spotted 65 sx plug 288-388'.
10 sx @ top of surface 0-15'.
Installed dry hole marker.
Ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bai H. Denny TITLE Production Foreman DATE 3-27-74

APPROVED BY John W. Ramsey TITLE Geologist DATE 001 3-27-74

CONDITIONS OF APPROVAL, IF ANY: