

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

E*
re-

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 0149818	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 1860 Lincoln Street, Suite 1200, Denver Colorado		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FEL and 1980' FSL		8. FARM OR LEASE NAME Anderson Federal	
14. PERMIT NO.		9. WELL NO. #1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT Vada (Penn)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9-T9S-R35E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

RECEIVED

1977

GEOLOGICAL SURVEY

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Mirupu, took stretch, shot 5-1/2" at 4462'-free.
2. Spotted 100 sx plug at 4,462'.
3. Shot and pulled 1,180' of 8-5/8".
4. Spotted 75 sx plug at 1,180'.
5. Spotted 75 sx plug at 430'.
6. Spotted 10 sx plug at surface and erected marker.

PTA 12-24-76

18. I hereby certify that the foregoing is true and correct

SIGNED A.A. Myers

TITLE Div. Production Manager

DATE 12-31-76

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

NOV 14 1977

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side