

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Blackrock Oil Company

3. ADDRESS OF OPERATOR
1000 V & J Tower, Midland, Texas, 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
Unit B, 660 FNL & 1980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
4028.6' G. L.

5. LEASE DESIGNATION AND SERIAL NO.
LC 069300

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N/A

7. UNIT AGREEMENT NAME
N/A

8. FARM OR LEASE NAME
Mobil Atlantic Fed.

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Allison Penn.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 10, T-9-S, R-36-E

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PLUG OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other) Perfs., acidizing & potential test.	☐		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Identify all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measures and true vertical depths for all markers and zones pertinent to this work.) *

- 1) Perf. 1 hole @ 9839', 9841', 9845', 9847', 9852', 9857', 9859', 9861', 9863' and 9865'. (10 holes)
- 2) Run 223 jts. 2" tbg. w/Baker R pkr. Set tbg @ 9788' w/pkr. @ 9721'. Acidize perfs. w/3000 gal. DS-30 & 12 ball sealers. P.I. 4.5 BPM @ 1500#. ISIP, 0#. Job complete @ 6:45 P.M. 8/22/70. Total load 153 BW. Well S.I. 12 hrs. SITP, 1100#. Connect well to test tank. Flowing on 24/64" choke. T.P., 300#, 24 hrs. IPT ended @ 10:00 A.M. 8/24/70. Flowed 388 BC, 46 BW. GOR, 1072. Gravity 46.2° API. Building tank battery.

18. I hereby certify that the foregoing is true and correct

SIGNED Peggy L. Holden

(This space for Federal or State office use)

TITLE Peggy L. Holden, Agent

DATE 8-27-70

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 31 1970

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO