

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3774

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator John L. Cox	8. Farm or Lease Name Shell G State
3. Address of Operator Box 2217, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>AN</u> , 1980 FEET FROM THE West LINE AND 510 FEET FROM THE South LINE, SECTION 4 TOWNSHIP 12-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat North Bagley (Penn.)
15. Elevation (Show whether DF, RT, GR, etc.) 4247' GR	12. County Lea

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Plugging Operations began 8-13-80.
2. Spotted 50 sx cement plug at 6300'. Tagged top of plug @5556'.
3. Spotted 15 sx cement plug at 4551'.
4. Recovered 4022' of 4-1/2" casing, 6128' left in hole.
5. Spotted 50 sx cement plug at 4050'. Tagged top of plug @3920'.
6. Spotted 50 sx cement plug at 3798'. Tagged top of plug @3626'.
7. Recovered 750' of 8-5/8" casing, 2998' left in hole.
8. Spotted 15 sx cement plug @838'.
9. Spotted 50 sx cement plug @804'. Tagged top of plug @620'.
10. Spotted 75 sx cement plug @448'. Tagged top of plug @344'. (398' of 12-3/4" casing left in hole).
11. Spotted 10 sx cement plug @surface with marker.
12. Hole filled with mud laden fluid.
13. Plugging operations completed August 19, 1980.

### 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Muelo Huitan</u>	TITLE <u>Production Manager</u>	DATE <u>9-30-80</u>
APPROVED BY <u>David Catano</u>	OIL & GAS INSPECTOR	DATE <u>AUG 19 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		