INCLINATION REPORT

OPERATOR_	Saxon Oil (ompany AD	DRESS 600 1sz	t Nat'L Bank B.	lda, Abilene, Tx.
LEASE <u>Gre</u>	ojo Dodd	WELL N	0. 1 FIELD		
LOCATION_	Section 30.	7-9-S. R-33-E.	Lea County, N	lev Mexico	
Depth 372 740 1100 1385 1740 2140 2450 2587 2981 3339 3605 3628 4050 4172 4263 4305		Angle clination 'degration '1/2 1/2 1/2 1/2 1/4 1/4 3/4 3/4 1/4 1/4 1/2 1/2 1/2 1/2 1/2 1/2	rees) Dis	placement 3.2364 3.2364 3.2016 3.1320 2.4795 3.0885 3.4800 1.3640 .6028 1.7336 4.6898 3.4846 .9812 .9768 1.0614 .7917 .3654	Displacement Accumulated 3.2364 6.4380 9.5700 12.0495 15.1360 18.6180 19.9820 20.5848 22.3184 27.0082 30.4928 31.4740 32.4508 33.5122 34.3039 34.6693
		t the above da owledge and be	Cac Ken Hedrick	tus Drilling	company alma
Affidavit:	;		·		
known to m on making behalf of best of hi	ne to be th deposition the operat is knowledg	signed authori e person whose , under oath s or of the well e and belief s ue vertical wh	name is su tates that identified uch well wa	bscribed her he is acting above, and s not intent	rebelow, who, for and in that to the ionally
Sworn and subscribed to in my presence on this the 7th day of					
July	19 72 MY COMMISSIO	N EXPIRES MARCH 30, 19	Notary Pu of Lea, S	blic in and tate of New	for the County Mexico

Seal

RECEIVED

(... 1 - 1770

OIL CONSTRUCTION CLAIM.