

M-G-F DRILLING Co., INC.

1126 VAUGHN BUILDING

MIDLAND, TEXAS 79701

915 - MU 4-7121

INCLINATION REPORT


OPERATOR: Stallworth Oil & Gas Co.
407 W. Missouri
Midland, Texas 79701

LOCATION: Midwest State # 2
1980' FWL & 1980' FNL,
Section 2, T-9-S, R-33-E,
Lea County, New Mexico.


Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees
250	1/4	4400	1/4	8270	3/4		
380	1/2	4850	1/4	8590	3/4		
880	1/4	5020	1/2	8997	1/4		
1372	1/2	5490	3/4	9310	1/2		
1860	1/2	5817	1 1/2	9610 TD	1/4		
2315	1/2	6119	1 1/2				
2500	3/4	6480	1 1/2				
2800	3/4	6900	1 1/2				
3300	3/4	7398	1				
3650	3/4	7624	1				
4015	3/4	7919	1				

STATE OF TEXAS
COUNTY OF MIDLAND

The undersigned states that he has knowledge of the facts and matter herein set forth and that the same are true and correct.


L. E. Grimes, Drilling Superintendent

SUBSCRIBED AND SWORN TO BEFORE ME this the 19th day of July, 19 74.


Notary Public in and for Midland
County, Texas

My Commission Expires:

June 1, 1975