NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S.G.S.	Form C+103 Supersedes Old C-102 and C-103 Effective 1-1-65 Su, Indicate Type of Lease
LAND OFFICE OPERATOR	State X Fea .
SUNDRY NOTICES AND REPORTS ON WELLS NOT USE THIS FORM FOR FOR FOR DOTALS TO DWALL OF TO CLIPTIN CA PLOW DARY TO A DIFFERENT RESERVOIR.	0G-1294
I. OIL X GAS OTHER.	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	b. Farm of Lease Haine Flying M State
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No.
4. Locution of Well UNIT LETTERN	10. Field and Pool, or Wildcat Flying M San Andres
THE West LINE, SECTION 20 TOWNSHIP 95 RANGE 33E NMPM.	
4358.5' GR	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Othe NOTICE OF INTENTION TO: SUBSEQUENT	er Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. X PULL OR ALTER CASING CMANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER	
17. Describe Projected or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1 103.	
 Spudded 12¹/₄" hole @ 4:00 PM 8/17/76. Fin drlg 12¹/₄" hole to 372' @ 2:00 AM 8/18/76. Ran 9 jts 8-5/8" OD 24# K-55 ST&C csg w/FC @ 284', set csg @ 371'. Cmtd 8-5/8" OD csg w/150 sx Cl H cont'g ¹/₄# celloflake & 2% CaCl, followed by 150 sx Cl H cmt cont'g 2% CaCl. PD @ 8:55 AM 8/18/76. Circ 35 sx cmt to surf. WOC 13 hrs. Cmtd surface csg in accordance w/OCC cmtg Option No. 2 in the following manner: Volume of cmt slurry was (177 cu ft) of Cl H cont'g ¹/₄# celloflake & 2% CaCl, followed by (177 cu ft) of Cl H cont'g ¹/₄# celloflake & 2% CaCl, followed by (177 cu ft) of Cl H cont'g ¹/₄# celloflake & 2% CaCl, followed by (177 cu ft) of Cl H cont'g 2% CaCl. Circ 41 cu ft to surface. Approximate temperature of cmt slurry when mixed was 81° F. Estimated minimum formation temperature in zone of interest was 64° F. Estimate of cmt strength @ time of csg test was 1200#. Actual time cmt was in place prior to starting test was 13 hrs. 	
Pressure tested cmt to 1000# for 30 mins. Tested OK. Resumed drlg 7-7/8"	hole @ 10 PM 8/18/76.
8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
tenco Dist. Drlg, Supv.	DATE <u>8/24/76</u>
PROVED BY TIPLE	1936 26 1976

.

.

.

CONDITIONS OF APPROVAL, IF ANYI