······································		·			
NO. OF COPIE	—			Form C-103	
DISTRIE	SUTION			Supersedes Old C-102 and C-103	
SANTA FE		NEW MEXICO OIL CON	ISERVATION COMMISSION	Effective 1-1-65	
FILE					
U.S.G.S.				5a. Indicate Type of Lease	
LAND OFFI	CE			State Fee X	
OPERATOR				5. State Oil & Gas Lease No.	
(DO N	SUNDR' OT USE THIS FORM FOR PROF USE "APPLICATE				
1.		······································		7. Unit Agreement Name	
OIL X	GAS WELL	OTHER-			
2. Name of Ope	erator			8. Farm or Lease Name	
Souther	n Union Explorat	tion Company		Shell Groebli Et Al	
3. Address of (Operator			9. Well No.	
Suite 1	800 1st Internat	tional Bldg., Dallas, T	exas 75270 ^	1	
4. Location of	· · · · · · · · · · · · · · · · · · ·			10. Field and Pool, or Wildcat	
	B 18	B40 FEET FROM THEEast	520	Flying "M" San Andres	
UNIT LETTI	ER ,	FEET FROM THE	LINE AND FEET FROM		
	North	30 <u>50 500000000000000000000000000000000</u>	6 33 E		
THE	LINE, SECTION	4 TOWNSHIP) NMPM. RANGE NMPM.	AIIIIIIIIIIIIIIIIIIIIIIA	
fulling	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12. County	
		4367.2 G. L.		Lea	
16.	Charle A	ANNA Bar Talli			
			Nature of Notice, Report or Otl		
	NOTICE OF IN	TENTION TO:	SUBSEQUENT	REPORT OF:	
			। 		
PERFORM REME		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY A	BANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER	CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB		
			OTHER		
OTHER					
17. Describe P	roposed or Completed Ope	erations (Clearly state all pertinent de	tails, and give pertinent dates, including	estimated date of starting any proposed	
work) SEE	RULE 1103.		and, and give permiting dates, including	estimated date of starting any proposed	
	Cleaned hole to				
)3/06/79 F	Perforated from	4308' to 4351' and 436	2' to 4378' (ISPF). Acid	dized with 5000 gallons.	
C C	Swab tested at r	ate of 4 BPH. Shut we	11 in to set test pump.		
	Test pumping at 44 BFPD, 75% oil.				
	Pumping 15 BWPD with trace of oil and slight gas.				
)4/04/79 F	Ran Cardinal Tra	icer survey, showed cha	nneling behind pipe, acid	d job went up and down	
Ł	behind pipe but	not out into formation	•		
)4/05/79 A	Attempted squeeze to shut in channels, used 100 sacks of Class "C" cement, no squeeze.				
4/06/79 A					
			rated from 4308' to 4351	'. Reacidize using	
	5000 gallons.	*			

18. I hereby certify that the information al SIGNED COLOR OF STATES	bove is true and complet t_3/μ	te to the best of my knowledge and belief.
APPROVED BY	Orig. Signed by Les Clements Oil & Gas Insp.	TITLE APR 27 1979

RECEIVED

APR2 6 1979 OIL CONSERVATION COMM. BOBBS, N. M.