

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Belco Petroleum Corp.

3. ADDRESS OF OPERATOR

411 Petroleum Building, Midland, Tx 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See spec 17 below.)

AT SURFACE: 1909 FSL, 2051 Sec 31, T9S

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) SI Evaluating additional pay

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2/13/81 SI. Well has been SI since April 14, 1980. An evaluation of lower zones is currently in progress. Well SI with 2 7/8" tubing in hole with a Halliburton RTTS packer set at 4100'. A 2000 psi well head is on the surface and a full open master valve is screwed onto the tubing.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE District Manager

DATE 2/13/81

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

ACTING DISTRICT ENGINEER

TITLE

DATE

FEB 24 1981

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 10 1931

OIL CONSERVATION DIV.