

11. Topography

- A. The wellsite and access route are located in a flat plain.
- B. The top soil at the wellsite is sandy.
- C. The vegetation cover at the wellsite is moderately sparse with prairie grasses, some yucca and miscellaneous weeds.
- D. No wildlife was observed, but it is likely that rabbits, lizards, insects and rodents traverse the area.
- E. There are no ponds, lakes, streams, or rivers within several miles of the wellsite.
- F. The wellsite is located on Federal surface.
- G. There is no evidence of any archaeological, historical or cultural sites in the vicinity of the location.

12. Operator's Representatives

- A. The field representatives responsible for assuring compliance with the approved surface use plan are:

Rhonda Operating Company
511 North Mail
Midland, Texas 79701
Telephone: (915) 682-5346 (office)

Ralph H. Viney
Telephone: (915) 683-1003 (residence)

Scott Davis
Telephone: (915) 697-3812 (residence)

Adam Praisnar
Telephone: (915) 682-1117 (residence)

Saeed Afghahi
Telephone: (915) 683-7390 (residence)

13. Certification

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed by Rhonda Operating Company and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved.

Date

2/22/1980

Saeed Afghahi