

Blue Quail No. 1 (cont.)

9-22-81

Completed laying down drill collars. Ran 217 joints of 2 7/8" tubing in hole to 6835' depth. Rigged down well service unit to evaluate options.