

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-101  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company		8. Farm or Lease Name State SG 25
3. Address of Operator 7990 IH 10 West, San Antonio, Texas 78230		9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>600 660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Cuerno Largo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4276.4 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Spud well at 9:00 p.m. 1/9/87. Ran 10 jts of 13 3/8" 54.5 #K55 STC casing (362.65') set at 380'. Cemented w/390 sacks of Class C w/2 % CaCl<sub>2</sub>. Circulated 140 sacks to pit. Top of cement at surface. Pumped plug down at 9:30 A.M. at 900 psi on 1-10-87. WOC 30 hrs., tested casing + BOP to 900 psi. Held OK. Resumed operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Don Smidsey TITLE Division Drilling Engineer DATE 1/20/87

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 26 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JAN 23 1987  
OCD  
HODRS OFFICE