STATE OF NEW MEXICO

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT



OIL CONSERVATION DIVISION HORRS DISTRICT OFFICE

September 1, 1988

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

GARREY CARRUTHERS

	rawer 1416
Snyder	, TX 79549
Gentleme	en:
Form C-J	.03, Report of Plugging, for your Indian Red #1-D 26-10-32
location	LEASE WELL $\#$ UNIT S-T-R be approved until a Division representative has made an inspection of the and found it to be cleared to comply with Division Rules and Regulations. The check each item in the space provided to indicate that the work has been done
() 1.	All Pits have been filled and levelled.
() 2.	Rat hole and cellar have been filled and levelled.
() 3.	A steep marker 4" in diameter and approximately 4' above mean ground level as been set in concrete. It must show the quarter-quarter section or unit designation, section, township, and range numbers which have been permanently stenciled or welded on the marker.
() 4.	The location has been levelled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
() 5.	The dead men and tie downs have been cut and removed.
() 6.	If a one well lease or last remaining well on lease, the battery and burn pit locations have been levelled and cleared of all junk and equipment.
location When all in the b	we are minimum requirements and no plugging bend will be released until all us for plugged and abandoned wells have been inspected and Forms C-103 approvel of the work outlined above has been done, please notify this office by fill plank form below and returning this letter to us so that our representative we to make more than one trip to the location.
Eddi	PLEASE SUBMIT THE FOLLOWING: 1) Fwo notarized copies of list of deviation surveys 2) One complete set of logs 3) Complete set of logs at bottom of C-105 with lithology of formations from surface to TD.
FILL IN	BELOW AND RETURN
I certif	y that the above work has been done and the
is ready	LEASE WELL # UNIT S-1 for your inspection and approval.
OPERATOR	

4 =14 = 8-7

STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

HOBBS DISTRICT OFFICE

September 1, 1988

Eddie they have relieve

GARREY CARRUTHERS

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

Patterson Petroleum Inc.
P.O. Drawer 1416
Snyder, TX 79549
Gentlemen:
Form C-103, Report of Plugging, for your Indian Red #1-D 26-10-32
LEASE WELL $\#$ UNIT S-T-R cannot be approved until a Division representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.
() 1. All Pits have been filled and levelled.
() 2. Rat hole and cellar have been filled and levelled.
() 3. A steep marker 4" in diameter and approximately 4' above mean ground level as been set in concrete. It must show the quarter-quarter section or unit designation, section, township, and range numbers which have been permanently stenciled or welded on the marker.
() 4. The location has been levelled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
() 5. The dead men and tie downs have been cut and removed.
() 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been levelled and cleared of all junk and equipment.
The above are minimum requirements and no plugging bond will be released until all locations for plugged and abandoned wells have been inspected and Forms C-103 approved. When all of the work outlined above has been done, please notify this office by filling in the blank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.
OIL CONSERVATION DIVISION PLEASE SUBMIT THE FOLLOWING: 1) Two notarized copies of list of deviation surveys 2) One complete set of logs 3) Complete formation record section at bottom of C-105 with lithology of formations from surface to TD.
FILL IN BELOW AND RETURN
I certify that the above work has been done and the LEASE WELL $\#$ UNIT S-T-R is ready for your inspection and approval.
OPERATOR
NAME & TITLE