State of New Mexico Submit 3 Copies Form C-103 to Appropriate
District Office Ene. , Minerals and Natural Resources Department Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-31904 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease STATE FEE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. L-494SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) State 1. Type of Well: GAS WELL WELL OTHER Dry 2. Name of Operator 8. Well No. Knox Industries, Inc. 3. Address of Operator 9. Pool name or Wildcat P.O. Box 3023 Midland, Texas 79702

4. Well Location Wildcat Unit Letter F: 1929 Feet From The North Line and 2026 Feet From The West Line 2 Township 9-S 33-E Section Range NMPM Lea County

	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4342.5 GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
ULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER:			OTHER:	
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. April 7, 1993 - Sitton Drilling Co. (Contractor) drilled well to total depth @ 8730'. We had no shows of any kind. Called Oil Conservation Division and received permission and directions to plug.  1) Lay down drill collars. Picked up 4 1/2" drill pipe. Ran in hole to 8730'. Dowell spotted 25 SX plug on bottom at 8730'.  2) Layed down drill pipe to 5000'. Spotted 25 SX plug  3) Layed down drill pipe to 8 5/8" casing. Spotted 50 foot in and 50 foot out of casing.  4) Layed down drill pipe to top of salt and spotted 100 foot plug.  5) Layed down all drill pipe and spotted 10 Sx plug in top. Welded on plate and monument. Release rig.  Rig moved out and location cleared and pits fenced. Ready for inspection.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE SIGNATURE	Proce pm	mi	Field Supervisor	DATE <u>4/16/93</u> (915)
TYPEORPRINT NAME Bruce L	. Groce			TELEPHONE NO.682-6261
(This space for State Use)	V. Wink		DIL & GAS INSPECTOR	SEP 2 0 1993
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:				
······································				<i>!</i> *
dim				ξ