

M. OIL CONS. COMMISSION
 FORM APPROVED
 BOX 1989
 BOX 1989
 FEBRUARY 28, 1995
 CASE DESIGNATION AND SERIAL

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

37 SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38.

GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
San Andres	4740	4780	No cushion, IF 15 min, 60.7 psi, ISI 58 min, ISIP 1582.7; FF 90 min, FFP 101.1 psi FSI 270 min, FSIP 1590.7 Recover 192' water.	Rustler	2214	2214
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 ISIP 1590.6 psi, FF 90 min, FFP 381.5 psi FSI 240 min; FSIP 1557.1 psi Recover 900' Drlg. fluid & form. water	Yates	2762	2762
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	San Andres	4127	4127
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Glorieta	5447	5447
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Hubb	6907	6907
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Abo Shale	7750	7750
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Abo Reef	8300	8300
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Wolfcamp	9098	9098
San Andres	4732	4876	No cushion, IF 15 min, 95.1 psi, ISI 60 min, ISIP 1590.4 psi, IF 120 min, FFP 440.5 psi, FSI 360 min, FSIP 3149 Recover 204' Drlg. mud & 408' form. water	Bough "C"	9783	9783
Morrow	11357	11378	2000' cushion, IF 15 min, IFF 681 psi ISI 64 min, ISIP 3172.2 psi; FF 90 min FFP 644.9 psi, FSI 180 min, FSIP 3530.9 psi Recover 2000' water blanket, no oil or gas.	Morrow	11240	11240
Morrow	11357	11378	2000' cushion, IF 15 min, IFF 681 psi ISI 64 min, ISIP 3172.2 psi; FF 90 min FFP 644.9 psi, FSI 180 min, FSIP 3530.9 psi Recover 2000' water blanket, no oil or gas.	U Miss.	11950	11950
Morrow	11357	11378	2000' cushion, IF 15 min, IFF 681 psi ISI 64 min, ISIP 3172.2 psi; FF 90 min FFP 644.9 psi, FSI 180 min, FSIP 3530.9 psi Recover 2000' water blanket, no oil or gas.	L Miss.	12160	12160
Devonian	12710	12842	3000' cushion, IF 15 min, 1114.5 psi ISI 62 min, ISIP 3237 psi, FF 60 min, FFP 1112.3 psi, FSI 118 min, FSIP 3932 psi Recover 3000' water blanket, no oil or gas.	Woodford	12732	12732
Devonian	12650	12853	3000' cushion, IF 15 min, IFF 1660 psi ISI 60 min, ISIP 4869 psi, FF 360 min FFP 1803 psi, FSI 390 min, FSIP 4881 psi Recover 35 bbls water cushion + 35 bbl oil	Devonian	12842	12842