

YATES PETROLEUM CORPORATION
Quetzal AQA State #1
Section 8-T11S-R33E
Lea County, New Mexico

TIGHT HOLE

RESULTS OF DRILL STEM TESTS:

DST #1 8605-8709' (Wolfcamp): TIMES: TO 20"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 206' of drilling mud. SAMPLER: 2600 cc mud. PRESSURES: IHP 4559;
IFP 147-189; ISIP 562; 2nd FP 128-138; 2nd SIP 967; FFP 147-161; FHP 4535