

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 22 1 11 PM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Exhausted Producer of Oil</b>		7. Unit Agreement Name
2. Name of Operator <b>Great Western Drilling Company</b>		8. Farm or Lease Name <b>SMAG</b>
3. Address of Operator <b>Box 1659, Midland, Texas</b>		9. Well No. <b>1</b>
4. Location of Well UNIT IS IN <b>N</b> <b>1980</b> FEET FROM THE <b>West</b> LINE AND <b>660</b> FEET FROM <b>South</b> LINE, SECTION <b>25</b> TOWNSHIP <b>8-S</b> RANGE <b>36-E</b> N.M.P.M.		10. Field and Pool, or Wildcat <b>Allison-Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4064 T.H.</b>		12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole was loaded with 10# mud. Plugs were spotted through 2' tubing as follows:

25 sacks of cement in 4½" @ 9640'.  
6047' of 4½" was cut and pulled.  
25 sacks were placed @ 6055'.  
25 sacks were placed @ 4150'.  
1006' of 7-5/8" was cut and pulled.  
25 sacks were placed @ 1020'.  
25 sacks @ 275'.  
10 sacks @ Surface.

A cleanup has been made and a proper marker placed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O.H. Crews TITLE Administrative Coordinator DATE March 21, 1966

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: