

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Robert A. Dean		Address 1005 Midland National Bank Bldg., Midland				
Lease Weathersby	Well No. 1	Unit Letter D	Section 24	Township 8-S	Range 24-E	
Date Work Performed	Pool Milnesand	County Roosevelt				

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. Spotted 2000 gal., acid over perforations 4554-70', 4580-96, 4604-20, used ball sealers, break down pressure 2400 psi to 2600 psi.
2. Fraced well using 20,000 gal. lease crude and 40,000 lb. 20/40 sand.

Witnessed by Robert A. Dean	Position	Company Robert A. Dean
---------------------------------------	----------	----------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 4253	T D 4675	P BTD 4617	Producing Interval 4554-4620	Completion Date
Tubing Diameter 2" EUE	Tubing Depth 4600	Oil String Diameter 5 1/2"	Oil String Depth 4675	
Perforated Interval(s) 4554-20, 4580-96, 4604-20				
Open Hole Interval None		Producing Formation(s) San Andres		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	12-9-61	6	1.2 MCF	2	200/1	-0-
After Workover	1-10-62	42.15	37.35 MCF	7	885/1	-0-

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

Name

Title

Position

Date

Company

Robert A. Dean**Robert A. Dean**