Form 9-331 a (Feb. 1951)		Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
•	E. W. STANDLEY UNITED STATES UNITED STATES ENSTRICT SUDEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	and Office Santa Fe

SUNDRY NOTICES AND REPORTS ON WELES

NOTICE OF INTENTION TO DRILL.	SUBSEQUENT REPORT OF CHARTEN SHUT-OFF			
NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ALTERING CASING			
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY			
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)				

			April 23 , 19 63
Well No. 1 is locate	d 660 ft.	fromS line	and 1980 ft. from $\left\{ \begin{matrix} E \\ W \end{matrix} \right\}$ line of sec. 18
04/4 DEC. 18	8- 5	36-E	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)
Uncesignated (Field)	Roos (C	ounty or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is **4146** ft.

ſ

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Federal-Silver #1: Drilling to TD of 9761' was completed 10-28-61. Verbal permission to plug was obtained 10-28-61 and plugging operations commanced. Cement plugs of 25 sx each were set at 9661-9760'; 7785-7885'; 4025-4125'; 2775-2875'; 1975-2075'. Cement plug of 15 sx set in surface. Hole filled with heavy mud between cement plugs: 2021' of 8-5/8" surface casing cemented to surface left in hole. Regulation U.S.G.S. marker was installed at surface. Location was cleaned up ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.					
Company	Roden Oil Company	commenced.			
Address	P.O. Box 767				
	Midland, Texas	By HURCH			
		Title Agent			