



(SUBMIT IN TRIPLICATE)

OBRP

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC-060978**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Correction report	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 10, 1963

Jacobs Federal

Well No. **9** is located **1980** ft. from **N** line and **624.3** ft. from **EX** line of sec. **19**

SW/4 NW/4 Sec. 19
(1/4 Sec. and Sec. No.)

S. 8
(Twp.)

35 E
(Range)

T12N
(Meridian)

Undesignated
(Field)

Rockwell
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Filed to correct typographical error on Subsequent Report of Water Shut-Off Filed May 6, 1963.

Report stated that 4 1/2" casing was set at 4750 feet; correct depth is 4740 feet.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Chorro Exploration, Inc.**

Address **c/o Oil Reports and Gas Services**
Box 763

Hobbs, New Mexico

By **H. L. Smith**

Title **Agent**