

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved,
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-148085

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

HORTON FARM

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

MILNORSE SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

30-8-35 NMPM

12. COUNTY OR PARISH

13. STATE

ROOSEULT

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Production Company

3. ADDRESS OF OPERATOR
Box 100, N. M. 86240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
330' FNL x 1650' FWL Sec 30 (Unit C NE 1/4 NW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4229' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In an effort to restore oil production, propose to run retrievable bridge plug just above 4th casing seat (4686) to isolate open hole section 4689-4737' and shut off or decrease water production. Evaluate and restore to production.

Latest test - Pmp OBD + 90 BW 24 hrs.

TD-4737'

O-H 4689-4737'

4 1/2" CSA 4689'

PERFS: 4625-36', 45-50', 62-76'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

1972

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Q-1-4585-11
1- Div
1- Susp
1- RRY

*See Instructions on Reverse Side

RECEIVED

MAR 7 1972

OIL CONSERVATION COMM.
HOBBS, N. M.