

M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240



**Fina Oil and Chemical
Company**
6 Desta Drive, Suite 4400
Midland, Texas 79705
P.O. Box 2990
Midland, Texas 79702
(915) 687-0575

April 24, 1989

United States Dept. of the Interior
Bureau of Land Management
Roswell Resource Area
P. O. Drawer 1857
Roswell, New Mexico 80202-1857

Re: Lse No. NM0145685
Horton Federal ~~Unit~~ ^{WELLS}
Casing Test Program

Dear Sirs:


As requested, attached are procedures to test the casing integrity of the Horton Federal Unit Well Nos. 13, 30 & 32. Upon notice that these procedures have been approved, we will commence testing the wells. If there are any problems, please contact me at (915)688-0600.

Sincerely,


A handwritten signature in cursive script, appearing to read "Jerry Nevans".
Jerry Nevans

JWN:dll

Attachments



*needs to be
witnessed by
BLM.*



Horton Federal No. 13

7M-0145685
SWSE 30-89-35E

Procedure to Test Casing Integrity

1. MIRU pulling unit.
2. TIH w/4 1/2" packer on workstring. Set pkr @ 4660' (top perf is @ 4680').
3. RU pump truck and pressure up on tubing/casing annulus to 500 psi. Hold pressure for thirty minutes and record on pressure chart.
4. Release pressure and rig down pump truck.
5. Release packer and TOH w/workstring.
6. Submit test report and pressure chart to BLM.

JWN:dll
4-18-89

