

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0145685

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER	NAME CHANGED: FROM: PAN AMERICAN PETR. CORP. TO: AMOCO PRODUCTION CO. EFFECTIVE: 2-1-71	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION		8. FARM OR LEASE NAME Horton General
3. ADDRESS OF OPERATOR PO BOX 68, HOBBS, N. M. 88240		9. WELL NO. 13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT Billings and San Andres
990' FSL x 2248.74 FEL Sec. 30 (UNIT O, SW 1/4 SE 1/4)		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 30-8-35 NMPM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4224' R.D.B.	12. COUNTY OR PARISH 13. STATE ROOSEVELT N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance w/ Form 9-331 dated 7-31-67
remedial work performed as follows:

Perforated interval 4685'-4714' w/ 21SPF.
Gauged w/ 3000 gallons 15%.

Prior - Pump 1 BO + 15 BW 24 hours.

after - Pump 10060 + 149 BW 24 hours. GOR 112.

O.C. 8-8-67
Comp 8-14-67

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 17 1967

J L GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

O+4- USGS- H
1- NSW
1- SUSP
1- RRY