

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> <i>Drilling</i>	5. LEASE DESIGNATION AND SERIAL NO. NM 0145685
2. NAME OF OPERATOR <i>Am. American Petroleum Corp.</i>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <i>Box 68, Hobbs NM 88240</i>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	8. FARM OR LEASE NAME <i>USA Russell E. Horton</i>
14. PERMIT NO.	9. WELL NO. <i>26</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>4212' RDB</i>	10. FIELD AND POOL, OR WILDCAT <i>Milnesand San Andres</i>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>29-8-35 N.M.P.M</i>
	12. COUNTY OR PARISH <i>Roosevelt</i>
	13. STATE <i>N.M.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 12-19-64, 4 1/2" OD 9.5" J-55 Casing was set at 4706' (TD) with 250 sx. In con neat. Tested casing w/ 2100 psi for 30 minutes. Test O.K. Perforated 4672'-92' w/ 2 JSPF. Acidized w/ 750 gal.

On PT flowed 95 BO & 0 BW in 14 hours thru 16/64" Choke. TPF 175 Cgr. 29°

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

