

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-11424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. N.M. 0145685	
2. NAME OF OPERATOR Elv American Petroleum Corp		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 68 Hobbs N.M. 88240		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL X 990' FEL, Sec. 29, (Unit H, SE 1/4 NE 1/4)		8. FARM OR LEASE NAME USA RUSSELL E HORTON	
14. PERMIT NO.		9. WELL NO. 29	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) NVA		10. FIELD AND POOL, OR WILDCAT MILNESAND SAN ANDRES	
18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-8-35 NMPM	
NOTICE OF INTENTION TO:		12. COUNTY OR PARISH ROOSEVELT	
TEST WATER SHUT-OFF <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> WATER SHUT-OFF <input checked="" type="checkbox"/> REPAIRING WELL <input type="checkbox"/>		13. STATE N.M.	
FRACTURE TREAT <input type="checkbox"/> MULTIPLE COMPLETE <input type="checkbox"/> FRACTURE TREATMENT <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>			
SHOOT OR ACIDIZE <input type="checkbox"/> ABANDON* <input type="checkbox"/> SHOOTING OR ACIDIZING <input type="checkbox"/> ABANDONMENT* <input type="checkbox"/>			
REPAIR WELL <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> (Other) <input type="checkbox"/> Spudding			
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting; any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co. spudded 12 1/4" hole at 11:15 AM on 11-29-65. At 5:35 PM, 8 7/8" OD 24# J-55 casing was set at 415' with 225 Sx. In con neat. Cement circulated. After W.O.C. 18 hours, tested casing with 1500 psi for 30 minutes. Test O.K. Reduced hole to 7 7/8" at 415' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct
(Original Signed by:)

SIGNED **V. A. STALRY** TITLE **Area Supt** DATE **2-1-65**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

DST (0+7)

0+4. USGS. Nobbs

e-JWB

e-Susp

e-2's

*See Instructions on Reverse Side

FEB 5 1965

**J. L. GORDON
ACTING DISTRICT ENGINEER**