

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
N.M. 0145685

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pan American Petroleum Corp

3. ADDRESS OF OPERATOR

Box 68, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)

At surface

990' FSL x 330' FWL, Sec. 29 (Unit M, SW 1/4 Sulf)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

VIA RUSSELL E. HORTON

9. WELL NO.

31

10. FIELD AND POOL, OR WILDCAT

MILNESAND SAN ANDRES

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

29-8-35 N.M.P.M.

12. COUNTY OR PARISH 13. STATE

ROOSEVELT N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

*At 5:00 P.M. on 3-28-65, Cactus Drilling Co
spudded 12 1/4" hole and at 11:45 P.M.
898' OD 24" J-55 Casing was set at 412'
w/ 225 St Incon Nept. Cement cire.
After H. O.C. 18 hours, tested casing
with 1500 psi for 30 minutes. Test
O.K. Reduced hole to 7 7/8" at 412'
and resumed drilling operations.*

18. I hereby certify that the foregoing is true and correct

Original Signed by:

SIGNED *V. E. STALEY*

TITLE *Area Sept*

DATE *3-30-65*

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

(0+7)
O+ 4-UGGS
C-JWB
C-SUSP
C-W/S

*See Instructions on Reverse Side

APPROVED

MAR 31 1965

J. L. GORDON
ACTING DISTRICT ENGINEER