Form 9-331
(May 1963)

Nov 9 / 08 PM '65

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO. NM 0108997(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR: Pan American Petroleum Corp

8. FARM OR LEASE NAME: J.F. FARRELL-USA

3. ADDRESS OF OPERATOR: Box 68, Hobbs, N.M. 88240

9. WELL NO. 2

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface

1980' FSL x 660' FWL, Sec. 28 (Unit L, NW/4 SW/4)

10. FIELD AND POOL, OR WILDCAT: CHAVEROO SAN ANDRES

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA: 28-7-33 NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.): 4439' R.D.B.

12. COUNTY OR PARISH: ROOSEVELT

13. STATE: N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☒	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other) Completion Operations			☒
(Other)				(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 10-23-65, 4½" OD 9.5# J-55 Casing was set at 4470' (TD) w/ 300 sx Incor Cement. TCMT 3700'. Tested Casing w/ 1500 psi for 30 minutes. Test O.K. Ran logs. Perforated intervals 4263, 4275, 4284, 4293, 4301, 4313, 4323, 4334, 4386 4393 x 4414 w/ 2 JSPF. Acidized w/ 2000 gallons LSTNE.

On swab test 10/29/65, well made 86 BO x 32 BW in 24 hours. Grav. 29°.

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By O. R. WILLIAMS, JR. TITLE Area Foreman DATE 10/1/65

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
NOV 12 1965
J. L. GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

OC-4-USGS
1-JWB
1-SOSP
1-RBY
2-Champlin, Box 1797, Midland
1-Warren American Oil Co Box 971, Midland
1-Kern Co. Land Co. [illegible] Midland
[illegible]