

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-11424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 010899(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Drilling**

2. NAME OF OPERATOR
Pan American Petroleum Corp.

3. ADDRESS OF OPERATOR
Box 68 Hobbs, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' FSL X 1900' FEL, Sec 28, (UNIT N, SW/4 SE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
J. F. FARRELL-USA

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT
CHAUEROO SAN ANDRES

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

28-7-33 NMPM

12. COUNTY OR PARISH
ROOSEVELT

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **Spudding**

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co. spudded 11" hole at 5:30 PM on 11/4/65. At 10: PM 8 5/8 OD 24" J-55 casing was set at 407' w/ 250 sx. Incor. Cement Circ. After N.O.C. 18 hours, tested casing w/ 1500 psi for 30 minutes, Test O. K.

Reduced hole to 7 7/8" at 407' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

**Original Signed by
J. L. GORDON**

TITLE

Area Supt

DATE

11-8-65

(This space for Federal or State office use)

TITLE

APPROVED

NOV 9 1965

**J. L. GORDON
ACTING DISTRICT ENGINEER**

*See Instructions on Reverse Side

04-USGS

2-Chapman
1-Kennedy
1-Warren
3-Tom Brown

1-JWB
1-SUSP
1-RRY