

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

APR 28 10 41 AM '66

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>1. Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>2. Name of Operator J.M. HUBER CORPORATION</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator Suite 922 Vaughn Building, Midland, Texas</p>		<p>8. Farm or Lease Name H.L. Harral</p>
<p>4. Location of Well UNIT LETTER N 800 FEET FROM THE South LINE AND 1840 FEET FROM THE West LINE, SECTION 17 TOWNSHIP 8S RANGE 36E NMPM.</p>		<p>9. Well No. 1-Y</p>
<p>10. Field and Pool, or Wildcat S. Prairie San Andres</p>		<p>11. County Roosevelt</p>
<p>12. Elevation (Show whether DF, RT, GR, etc.) 4128' GL</p>		<p>13. Other</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☒
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled to 5050' RTD. Ran 158 jts. 5-1/2", 15.5#, J-55, ST&C casing.
Perforated 4977-4990; 4990-4995; 4910-4927

PBTD 4944' after squeezing bottom two sets of perforations with 90 sx cement.

Please furnish plugging instructions with approval.

We would like to commence plugging immediately.

15 sxs. Over perms.

26 sxs. @ 5 1/2" Casing Stub

25 sxs. @ Base of salt section

25 sxs. @ Top of salt section

25 sxs. Across shoe of surface casing

10 sxs. @ Surface Mud between plugs.

Circ. w/200 sx Incor,
2% gel, 8% salt. Top
of cement 4080' from
Temp. Survey. WOC 4
days. Pressure test-
ed csg. @ 600 PSI for
30 min., held OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stan L. Menden

TITLE District Production Supt. DATE 4-25-1966

APPROVED BY Joe V. Barry

TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: