

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.
NM 0108997 (A)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER <u>Drilling</u>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <u>Perm American Petroleum Corp</u>		8. FARM OR LEASE NAME <u>J.F. FARRELL-USA</u>	
3. ADDRESS OF OPERATOR <u>Box 68, Hobbs, N.M.</u>		9. WELL NO. <u>6</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>660 FSL X 660 FEL, Sec. 28 (Unit P, SE 1/4 SE 1/4)</u>		10. FIELD AND POOL, OR WILDCAT <u>CHAUVERON-SAN ANDRES</u>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>28-9-35 NMPM</u>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH <u>ROOSEVELT</u>	
		13. STATE <u>NM</u>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) <u>Spudding</u> ☒	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co. spudded 11" hole at 5:30 PM on 11/26/65. On 11/27/65, 8 5/8" OD 24" J-55 casing was set at 392' w/ 250 qt. Cement circulated. After 400 18 hours, tested casing w/ 1500 psi for 30 minutes. Test O.K. Reduced hole to 7 7/8" at 392' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ Original Signed by: V. E. STALEY

TITLE Area Supt DATE 11/29/65

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED

DEC 2 1965

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

0-4-USGS
1-JWB
1-SUSP
1-RRY
2-Champlin
1-Warren Am
1-Perm Co
1-Min. Comm