

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM 0108997(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Pan American Petroleum Corp.	8. FARM OR LEASE NAME J.F. FARRELL-USA
3. ADDRESS OF OPERATOR Box 68, Hobbs, N.M. 88240	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL x 1980' FEL, Sec. 28 (UNIT, NW/4 SE/4)	10. FIELD AND POOL, OR WILDCAT CHAUEROO SAN ANDRES
14. PERMIT NO.	15. ELEVATIONS (Show whether D°, RT, GR, etc.)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 28-7-33	12. COUNTY OR PARISH ROOSEVELT
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co. spudded 11" hole at 11:00 PM on 12-15-65. On 12-16-65, 8 5/8" OD 24" J-55 casing was set at 395' w/ 200 sq. Incon. Neat. Cement circulated. After M. O. C. 18 hours tested casing w/ 1000 psi for 30 minutes. Test O.K.

Reduced hole to 7 7/8" at 395' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

V. A. STANLEY

TITLE

Area Supt

DATE

12-20-65

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DEC 23 1965

J. L. GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

0-4-USGS
1-JWB
1-SUSP
1-RK4

2-Champin Petro Co, Box 1747, Midland
1-Warren Amer. Oil Co. 424 - 1st State Bank Bldg, Midland
1-Kern Co Land Co. 418 " " "
3-Tom Brown Drilling 34451st, Midland