

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>E. L. Brown, Jr.</b>	8. Farm or Lease Name <b>Saunders "A"</b>
3. Address of Operator <b>704 Vaughn Building, Midland, Texas</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> , <b>1650</b> FEET FROM THE <b>West</b> LINE AND <b>1650</b> FEET FROM THE <b>North</b> LINE, SECTION <b>5</b> TOWNSHIP <b>8-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Elvitt San Andres</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4080' GR</b>	12. County <b>Hoodworth</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**This well was plugged and abandoned on February 5, 1968 as follows:**

**10 sacks cement at 4400'**

**Shot off 4-1/2" casing at 2196' and set 25 sacks cement at 2196'**

**25 sacks cement at 331'**

**10 sacks cement at the surface**

**Hole filled with 8.9# mud.**

**Erected steel marker.**

**Notification will be given when well site has been cleared and conditioned looking to final inspection and approval of abandonment.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **R. Busby** TITLE **Agent** DATE **February 12, 1968**

APPROVED BY **John W. Remyon** TITLE **Geologist** DATE **JUN 17 1968**

CONDITION OF APPROVAL, IF ANY: