

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☐ well ☐ other Injection

2. NAME OF OPERATOR

Champlin Petroleum Company

3. ADDRESS OF OPERATOR

P.O. Box 7946 Midland, Texas 79709

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FSL & 660 FWL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☒

☐

5. LEASE

Federal No. 0554778

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lauck - Federal

9. WELL NO.

10

10. FIELD OR WILDCAT NAME

Chaveroo - San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 29, T 75, R 33

12. COUNTY OR PARISH

Roosevelt

13. STATE

TX

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4403 WD

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 2-16-85 1. Set 4 1/2" CIBP 24100' - Cap with 50" cement  
2-16-85 2. Spot 30 sxs cement 22350' - Tag 22003'  
2-16-85 3. Spot 30 sxs cement 21900' - Tag 21730'  
2-17-85 4. Pull 1010' of 4 1/2" casing - Spot 45 sxs 21060' - Tag 2915'  
2-17-85 5. Spot 45 sxs 2420' - Tag 2251'  
2-17-85 6. Spot 50' surface and dry hole marker  
All plugs set thru tubing  
Hole loaded with 10#/gal mud

Donald W. Tally, Jr.  
D. W. Tally, Jr.

Champlin Petroleum Co.  
Senior Engineer

2-28-85

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

VP Mayo Harris Casin

Pullin, Inc.

DATE

2-28-85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:


Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

APPROVED  
PETER W. CHESTER

FEB. 2 1987

\*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA



R

RECEIVED  
FEB 9 1967  
OCE  
HOBBS OFFICE