

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well
2. NAME OF OPERATOR
Tenneco Oil Company
3. ADDRESS OF OPERATOR
6800 Park Ten Blvd., San Antonio, TX. 78213
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 660' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- | | | |
|--------------------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input type="checkbox"/> |
| (other) Returned to production | | <input checked="" type="checkbox"/> |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Put well back on production on 3-1-80 without changing and lowering pump.

5. LEASE NM-0127782	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
7. UNIT AGREEMENT NAME -----	
8. FARM OR LEASE NAME Federal 27	
9. WELL NO. 3	
10. FIELD OR WILDCAT NAME Chaveroo San Andres	
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA 27 T7S R33E NMPM	
12. COUNTY OR PARISH Roosevelt	13. STATE N.M.
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 4382.2 GR	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

MAR 28 1980

**U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO**

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Mary Hall

TITLE Production Analyst

DATE 3/24/80

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE