NO. OF COPIES RECEIVED			
DISTRIBUTION	-	*	Form C-103 Supersedes Old
SANTA FE		CERVATION COMMENTAL	C-102 and C-103
FILE		SERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	-1		5a. Indicate Type of Lease
LAND OFFICE	-1		
OPERATOR	-		
			5. State Oil & Gas Lease No. K-2671
USE "APPLIC.	RY NOTICES AND REPORTS ON ROPOSALS TO DEILL OR TO DEEPEN OR PLUG ATION FOR PERMIT _" (FORM C-101) FOR SU	WELLS BACK TO A DIFFERENT RESERVOIR. (H PROPOSALS.)	
1. OIL X GAS WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
The Wiser Oil Company			State J
3. Address of Operator			9. Well No.
	7 Hobbs, New Mexico	o 88240	2
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTERG	1980 FEET FROM THE North	LINE AND FEET FROM	Chaveron SA
	TION 25 TOWNSHIP 7S	RANGE 33E NMPM	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
(1)	4320 GF	3	Roosevelt
16. Check	Appropriate Box To Indicate N	Nature of Notice Report of Ot	
NOTICE OF	INTENTION TO:		rer Data I REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	LOG OND ABARDUMMENT [X]
OTHER		OTHER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On April 4, 1977 went in $4\frac{1}{2}$ " casing with dump bailer and set 3 sx cement plug on top of CI bridge plug at 4131'. Went in with jet cutter ond severed casing at 3260'. Worked casing with hydraulic jacks but couldn't pull it. Circulated 140 bbls of fresh water around casing but it still wouldn't come loose. Run a freepoint and found casing completely stuck at 1204'. Went in with jet cutter and severed casing at 1238'. Pulled 1238' of $4\frac{1}{2}$ " casing. Went back in with tubing string to TD of 3310'. Circulated hole with 25 sx mud per 100 bbl of fluid. Spotted 100' cement plug across severed $4\frac{1}{2}$ " casing at 3260' using 12 sx cement. Pulled up to 1288' and spotted 100' cement plug in and out of $4\frac{1}{2}$ " casing stub using 25 sx cement. Pulled up to 416' and spotted 100' cement plug in and out of 8-5/8" casing and installed dry hole marker in accordance with New Mexico Oil Comm. rules. On May 5, 1977 location was leveled and all material removed from location. Plugging is complete and location ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED D. M. Angelay TITLE District Supt.	DATE 6-10-77	
APPROVED BY AND VALLE ANY:	DATE	

012282

OIL CONSERVING SHE STAR. HOBBS, N. M.