

UN ID M-T-GH CONS. COMMISSION
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS NEW MEXICO 88240
RECEIVED

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Milnesand Unit
2. NAME OF OPERATOR Breck Operating Corp.	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P.O. Box 911, Breckenridge, Texas 76024	9. WELL NO. 213
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter "D", 860' FNL & 660' FWL	10. FIELD AND POOL, OR WILDCAT Milnesand (San Andres)
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T-8S, R-35E
15. ELEVATIONS (Show whether OF, RT, GR, etc.) 4210' GR	12. COUNTY OR PARISH Roosevelt
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Set CIBP & Temp. Abandon X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

WELL HISTORY

8-5/8" 24# set @ 361' w/ 300 sx. in 12-1/4" hole. Cmt. circ.
4-1/2" 9.5# set @ 4820' w/ 250 sx. in 7-7/8" hole. TOC @ 3177'
Perforations: 4599'-4669'
TD: 4820'
PBTD: 4782'

Procedure

Set 4-1/2" CIBP @ 4575'
Pressure up on casing to test downhole integrity

Test to be conducted Wednesday, May 11, 1988

18. I hereby certify that the foregoing is true and correct

SIGNED Tom G. Duncan

TITLE Petroleum Engineer

DATE 4/20/88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED FOR 12-MONTH PERIOD
ENDING APR 28 1989
See Instructions on Reverse Side

APPROVED
DATE
PETER W. CHESTER
APR 28 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA