

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0164650

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WOLF FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CHAUEROO SAN ANDRES

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

19-7-34 NMPM

12. COUNTY OR PARISH

ROOSEVELT

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

Box 68, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL x 2310' FEL, Sec. 19 (UNIT B, NW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4329' R. D. B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD- 4345. On 8-5-66, 4 1/2" OD 9.5" J-55 Casing was set at 4345' w/ 500 sq 12% Gel + 300 sq. Incon Cement. Tested casing w/ 2000 psi for 30 minutes. Test O.K.
PBD 4315. Perforated intervals 4083-94, 4149-52, 68-77, 81-83, 88-02, 4241-71 w/ 2JSPF. 2" log @ 4282'.
Acidized w/ 2000 gallons. Trace w/ 30,000 gal oil, 40,500# sand, 3000# beads.

On PT. pumped 42 BLD x 81 BNO x 2 BW in 24 hours.
GOR 621. Cgr. 26.

TD- 4345'

PBD- 4315'

TPA-4083' San Andres

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

8-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

04-4- USGS- 14
1- NSW
1- SUSP
1- R12y

*See Instructions on Reverse Side

APPROVED

AUG 25 1966

J. L. GORDON
ACTING DISTRICT ENGINEER