

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions
verse side)

FE-
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0142393

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

Box 68, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1980' FNL * 660' FWL, Sec. 20 (UNIT E, SW 1/4 NW 1/4)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

HOMME Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Chaveroo San Marcos

11. SEC. T. R. M., OR B.E. AND
SURVEY OR AREA

20-7-34 NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OM, etc.)

4324' R.D. B.

12. COUNTY OR PARISH

ROOSEVELT

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL-OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 9-10-66, 4 1/2" OD 9.5" J-55 Casing was set at 4448' w/ 500 # 12% Gel + 300 # 70# Cement Circ. Tested casing w/ 2000 PSI for 30 minutes. Test OK. Perforated intervals 4093-94, 4108-12, 16-20, 47-49, 53-59, 73-75, 80-81, 85-86, 90-92, 94-99, 4204-06, 14-16, 18-21, 67-79, 86-94, w/ 2 SPF. Acidized w/ 2000 gal. Fraced w/ 30,000 gal oil, 40,500# Sand, 3000# beads. Evaluated.

On PT, 24 hours, flowed 141 BLO + 91 BNO, 24/6" CH 7 PF 2000 CPF 1000 GOR 512. Cgr. 25.

TD. 4448'

PBD - 4401'

TPV-4093-San Marcos. Comp. 9-21-66

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

9-22-66

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

SEP 23 1966

*See Instructions on Reverse Side

J. L. GORDON

ACTING DISTRICT ENGINEER

4 - USGS H0883
1 - NSW
1 - SUSP
1 - REV