

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TR  
(Other Instructi.  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Drilling

2. NAME OF OPERATOR  
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR  
Box 68, Hobbs NM. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
660' FSL x 2150.9' FEL. Sec 18 (UNIT 0, SW 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.  
NM 0164650

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
1866

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
WOLF FEDERAL

9. WELL NO.  
3

10. FIELD AND POOL, OR WILDCAT  
CHAUEROO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
18-7-34 NMPM

12. COUNTY OR PARISH  
Roosevelt

13. STATE  
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Squadding ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Chico Arly Co. squadded 12 1/4" hole 9:30 am 9-21-66.  
At 6: PM, 8 3/8" OD 24" J-55 Casing was set at 450'.  
w/ 300 sq. Incer. Cement circulated. After  
HOC 18 hours, tested casing w/ 1000 psi for  
30 minutes. Test OK.

Reduced hole to 7 7/8" @ 450' and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0+4-USGS-1  
1-N3W  
1-SUSP  
1-R124

\*See Instructions on Reverse Side

SEP 29 1966  
J. L. GORDON  
ACTING DISTRICT ENGINEER