

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HUBBARD FIELD O.G.C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 AUG 15 11 44 AM '67

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG - 848
7. Unit Agreement Name
8. Farm or Lease Name Sinclair "B"
9. Well No.
10. Field and Pool, or Wildcat
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Charles B. Read
3. Address of Operator P. O. Box 2126, Roswell, New Mexico
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 7S RANGE 34E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4324KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER C-105 <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total depth of 4650 was reached 5/30/67 and the test was P & A on 5/30/67. Cement plug of 25 sx at 4550-4650, 25 sx at 2260-2360, 25 sx at 375-425 (in and out of surface casing), 10 sx at surface. Heavy mud spotted between plugs. No attempt made to pull surface casing. Cut and covered pits. Installed dry hole marker. Location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles B. Read TITLE Operator DATE August 15, 1967
 APPROVED BY [Signature] TITLE SUPERVISOR DATE _____
 CONDITIONS OF APPROVAL, IF ANY: