

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM-0321281	
2. NAME OF OPERATOR Am American Petroleum Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 68 Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL X 660' FWL, Sec. 29 (Unit M, SW 1/4 SW 1/4)		8. FARM OR LEASE NAME PETERSON "A" FEDERAL	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4142' RDB		10. FIELD AND POOL, OR WILDCAT TODD LOWER Sim Andres	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-7-36 NMPM	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE N.M.	

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 11-18-67, 4 1/2 OD 24" J-55 casing was set at 4329' w/300 SK. incor neat. Tested casing w/3000 PSI for 30 minutes. Test OK. Perforated internals 4247-56, 4260-67, 4270-86 w/2-TSPF. Acidized w/4000 gal. 20%. Evaluated.

On P.T., 23 hours, pumped 118 BO X 2 BLW. GOR-528 CGR-26.1

T.D. - 4329

P.D. - 4302

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DEC 5 1967

0+4 - USGS - Roswell
1 - NSD
1 - SUSP
1 - RY

*See Instructions on Reverse Side J L GORDON
ACTING DISTRICT ENGINEER