Form approved. Budget Bureau No. 1004-0135 N. MacCharle Cars, TACON HOH? 80<del>.m</del>m 3160—5 UNI D STATES Expires August 31, 1985 November 1983: DEPARTMENT OF THE INTERIOROF AND THE PROPERTY OF THE INTERIOR S. LEASE DESIGNATION AND SERIAL NO. Formerly 9-331) NM041698A BUREAU OF LAND MANAGEMENTHOBBS, NEW MEXICO INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS, (Do not use this form for proposals to drill or to deepen or plug back to a different desertion use "APPLICATION FOR PERMIT—" for such proposals.) UNIT AGREEMENT NAME Bhuitt San Andres Unit GAS WELL OTEZE NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY 9 ADDRESS OF OPERATOR WELL NO. 9 415 W. WALL, SUITE 1000 MIDLAND, TX 79701 LOCATION OF WELL (Report location clearly and in accordance with any State requirements." 10. FIELD AND POOL, OR WILDCAT See also space 17 below.)
At surface Bluitt San Andres Assoc. 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA Unit Letter I, 1980' FSL & 660' FEL API # 30-041-20250 Sec. 14, T8S, R37E 15. ELEVATIONS (Show whether DF, RT, CR. etc.) 14. PERMIT NO 12. COUNTY OR PARISH: 13. STATE Roosevelt NM 16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SECT-OF PULL OR ALTER CASING WATER SHCT-OFF REPAIRING WELL MULTIPLE COMPLETE FRACTUBE TREAT FRACTURE TREATMENT ALTERING CASING Х SHOOT OR ACIDIZE SHOOTING OR ACIDIZING ABANDON MENT Casing integrity REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertiproposed work. If nent to this work.) 6-16-94 Well had no production equipment in the hole. Lay down 1 jt of tbg & valve. Set CIBP @ 4346' w/ 2 sx cement on top 6-28-94 Tested casing to 500 psi for 30 min, held ok Chart attached. BLM was notified of test, but did not witness. Request TA status as per PPOC's meeting with Tony Ferguson on 3-21-94 and subsequent letter dated 3-29-94

