Form 9-331 N. M. CIL CONS. COMMISSION	orm Approved.
P. O. DOX 10 NITED STATES	Budget Bureau No. 42-R1424 5. LEASE
HOBES NEW MEXICO 88240	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	-
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT & GREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil well ℜ well □ other	Federal
	9. WELL NO.
2. NAME OF OPERATOR	2
Tom Brown, Inc.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Vada Penn
P.O. Box 2608 Midland, Texas 79702-2608 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec. 33-T8S-R36E
AT SURFACE: 660' FNL & 1980' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Roosevelt New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
PULL OR ALTER CASING TO MAR 8	charge on Form 9-330)
MULTIPLE COMPLETE	HOO change on Form 9-330.)
CHANGE ZONES	048
ABANDON* S MINERALS MG (other)	
ROSWELL, N	EW MEXICO
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent All Complete C	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and to this work $)^*$
09-23-82 - MI & RU well service unit. Pulled & L	D pump & rods. Pulled & ID the
09-28-82 - Set CIBP @ 9700' with 25 sxs cmt from 10# mud.	9700'-9370'. Displaced hole with
10-02-82 - Cut 4 1/2" csg @ 4296' & pulled 111 j	ts of same.
10-05-82 - Spot 60 sxs cmt plug @ 4541' - 4240'.	Spotted 50 sxs cmt plug @ 4050'
did not tag top. Spotted another 50 s	xs emt plug @ 4050' - 3860'
10-06-82 - Cut 8 5/8" csg @ 996' & bulled 24 its	of same.
10-07-82 - Spotted 70 sxs cmt plug 3 1050' - 890' 457' - 345'.	'. Spotted 70 sxs cmt plug @
10-08-82 - Spotted 25 sxs cmt plug d surface. Ins well service unit.	stalled Dry Hole marker. RD & rel
Location has been inspected by Surface owner, see	e attached letter.
Subsurface Safety Valve: Manu. and Type	
	- · · · · · · · · · · · · · · · · · · ·
18. I herefor certify that the foregoing is true and correct	
SIGNED Cand TITLE Southern Divis	sion March 4, 1983
	erintendent
APPROVED (This space for Federal or State offic	Ce use:
CONDITIONS OF APPROVAL, IF ANY:	DATE
MAR 8 195.3	
FOR	
JAMES A. GILLHAM . See Instructions on Reverse Si	da
DISTRICT SUPERVISOR	

I N