

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-1371-1 & L-737	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator The Maurice L. Brown Company		8. Farm or Lease Name Blond State Comm.
3. Address of Operator Suite 200/Sutton Place Bldg. Wichita, Kansas 67202		9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>8-S</u> RANGE <u>35-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4212.6 GR		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-7-84—Well quit pumping.

7-10-84 through 7-11-84—Attempted to change pump. Could not lower replacement pump below approximately 7400'. Picked up on tubing. Tubing stretch indicated tubing stuck several thousand feet off bottom.

7-19-84 through 7-24-84—Ran free point. Tubing was stuck at 7366'. Cut tubing at 7477' and backed off tubing in collar at 7303'. Ran overshot, bumper sub, hydraulic jars, 4-3 1/2" OD drill collars and accelerator sub. Latched onto tubing collar at 7303' depth and attempted to jar tubing section (7303' to 7477') out of collapsed casing. Tubing did not move with two days jarring. Released overshot and pulled out of hole. Laid down all fishing tools. Ran tubing back in hole and rigged down well service unit.

Well temporarily abandoned on 7-24-84.

An application to plug and abandon will be submitted in the near future.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. Groesbeck TITLE District Engineer DATE 7-25-84

ORIGINAL SIGNED BY JERRY SEAYON

DISTRICT SUPERVISOR

TITLE

DATE

JUL 27 1984

CONDITIONS OF APPROVAL, IF ANY:

Expires 7/27/85