

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION SERIAL NO.

M-23054

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal H

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5, T-3-S, R-37-E

12. COUNTY OR PARISH 13. STATE

Roosevelt New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

H. L. BROWN, JR.

3. ADDRESS OF OPERATOR

Post Office Box 2237, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FEL and 1650' FSL, Sec 5, T-3-S, R-37-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4051.3 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING Casing

ABANDONMENT*

Process

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including proposed date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for markers and zones pertinent to this work.)*

Drld to a total depth of 3156'. Ran 195 jts 4 1/2" OD 10.50 & 11.50" K-55 ST< csg(3172') set at 3156'. Cemented with 600 sx 50-50 Class H and A Pozmix with 6#/sx salt & 0.75% CFR-2/ sx. Bumped plug @ 2:30 PM, 2-15-77. Cut off 4 1/2" csg. Nipped down & cleaned bits. Released rig at 8:00 PM, 2-15-77. Ran temperature survey. Found cement top behind 4 1/2" csg @ 5490'. PBTD @ 3094'. WOC 14 hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED Jan Davidson TITLE Production ClerkDATE 2-16-77

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD

DATE FEB 22 1977U.S. GEOLOGICAL SURVEY
DALLAS, NEW MEXICO